

CRITICAL ITEMS LIST

ASSY NOMENCLATURE: GAS CONTAINER ASSEMBLY

ASSY P/N: 40014G-01AY

SYSTEM: CREW ESCAPE SYSTEM

SUBSYSTEM: LAUNCH ENTRY SUIT

REVISION

PAGE 24 OF 60

FMEA		NAME, QTY & DRAWING REF DESIGNATION	CRAFT	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	RATIONALE FOR ACCEPTANCE
REF	REV					
3.8.1		GAS CONTAINER ASSEMBLY (Counter Pressure Garment) #1, 18951G-02	I/1	3.8.1 Mode: Leakage or separation of gas bladder Cause: # overstress # defective material	Unable to maintain suit pressure	<p>1. DESIGN FEATURES TO MINIMIZE FAILURE MODE</p> <ul style="list-style-type: none"> a. Material is polyurethane b. The gas container is ultrasonic (heat) sealed c. The restraint layer and restraint cover are exterior to the gas container and function as protective covers. d. This configuration is currently used in various Department of Defense flight suits e. The configuration is utilized in the extravehicular mobility unit <p>2. TEST OR ANALYSIS TO DETECT FAILURE MODE</p> <ul style="list-style-type: none"> a. <u>Acceptance Testing</u> <ol style="list-style-type: none"> (1) Production lot samples are tested to ensure the desired construction strength (2) Leak tested at 30 ± 0.2 psig for 15 minutes, 130.0 scm/minute maximum allowable leak rate. (3) Proof pressure tested at two times the operational pressure. (4) Restraint and gas container are structural tested at 5.6 ± 0.2 psig for 15 minutes (5) Coverall assembly system pressurization/leak test system #1: 2,400 scm/minute maximum at 145.0 ± 10.0 mmHg (6) Coverall assembly system pressurization/leak test system #2: 2,400 scm/minute maximum at 110.0 ± 10.0 mmHg b. <u>Certification Testing</u> <ul style="list-style-type: none"> a. Overstress test to four times operational pressure (7.8 psi) 11.2 ps

840210Q
ATTACHMENT VT
PAGE 8, OF 117

PREPARED BY: R. L. ALLISON

SUPERVISING DATE:

APPROVED BY: J. O. SCHLOSSER

DATE:

CEE/LES -24

CRITICAL ITEMS LIST

ASSY Nomenclature: GAS CONTAINER ASSEMBLY

ASSY P/N: 40014G-078Y

SYSTEM: CREW ESCAPE SYSTEM

REVISION

SUBSYSTEM: LAUNCH ENTRY SUIT

PAGE 25 OF 60

FMECA		NAME, QTY & DRAWING REF DESIGNATION	CRIT	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	RATIONALE FOR ACCEPTANCE
REF	REV					
3.8.1		GAS CONTAINER ASSEMBLY (Counter Pressure Garment) (I), 1B951G-02	1/1	3.8.1 Mode: Leakage or separation of gas bladder Cause: • overstress • defective material	Unable to maintain suit pressure	<ul style="list-style-type: none"> b. <u>Certification Test</u>. <ul style="list-style-type: none"> (1) High altitude chamber test, Brooks Air Force Base <ul style="list-style-type: none"> (a) Unmanned testing series <ul style="list-style-type: none"> 1 Gradual ascent/descent to 100,000 feet. 2 Rapid decompression to 90,000 feet. 3 Endurance runs rapid decompression to 100,000 feet for 37 minutes. (b) Manned testing series <ul style="list-style-type: none"> 1 Gradual ascent/descent to 100,000 feet 2 Rapid decompression to 90,000 feet. 3 Endurance runs rapid decompression to 100,000 feet for 37 minutes c. <u>Turnaround Test</u> (In accordance with PIA 20033) <ul style="list-style-type: none"> (1) Leak tested at 3.0 ± 0.2 psig for 15 minutes, 130 scd/minute maximum allowable leak rate. (2) Restraint and gas container are structural tested at 5.6 ± 0.2 psig for 15 minutes 3. INSPECTION <ul style="list-style-type: none"> a. One hundred percent verification of all cementing and stitching operations b. One hundred percent visual inspection for leakage. c. Visual inspection of link net for defects. d. One hundred percent inspection during assembly.

PREPARED BY: M.L. ATTISON

SUPERSEDING DATE

APPROVED BY: J.O. SCHLOSSER

DATE:

CEE/LES -25

3402100
ATTACHMENT - II
Page 82 of 117

CRITICAL ITEMS LIST

ASSY NOMENCLATURE: GAS CONTAINER ASSEMBLY
ASSY P/N: 40074G-01BY

SYSTEM: CREW ESCAPE SYSTEM
SUBSYSTEM: LAUNCH ENTRY SUIT

REVISION:
PAGE 26 OF 60

FMEA		NAME, QTY & DRAWING REF DESIGNATION	CANT'Y	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	RATIONALE FOR ACCEPTANCE
REF	REV					
3.8.1		GAS CONTAINER ASSEMBLY (Counter Pressure Garment) (1), 1B951G-02	1/1	3.8.1 Mode: Leakage or separation of gas bladder Cause: • overstress • defective material	Unable to maintain suit pressure	<p><u>Turnaround Inspection:</u> (In accordance with PIA 23033)</p> <ul style="list-style-type: none"> a. One hundred percent visual inspection for leakage. b. Visual inspection of link net for defects. <p>4. FAILURE HISTORY</p> <p>None. The gas container is used by the Air Force in high altitude suits for high performance aircraft and Dryden Flight Research Center.</p> <p>5. OPERATIONAL USE</p> <ul style="list-style-type: none"> a. Operational Effect of failure - Possible loss of crewmember. b. Crew Action - None. c. Crew Training - Not applicable. d. Mission Constraints - None. e. In-Flight Checkout - None. Crew could not repair or replace a defective gas container assembly.

S402100
ATTACHMENT
Page 93 of 117